


# Homescreen

#### Sample Site, Sample Street, Anytown, UK



The Property Ombudsman

<u>info@groundsure.com</u> ↗ 01273 257 755 Ref: Sample\_HomescreenP Your ref: Sample Grid ref: 123456 123456 Date: 23 February 2025





# Homescreen

### **Useful contacts**

East Suffolk Council: <u>https://www.eastsuffolk.gov.uk/</u> ↗ <u>customerservices@eastsuffolk.gov.uk</u> ↗ 0333 016 2000

Environment Agency National Customer Contact Centre (NCCC): <u>enquiries@environment-agency.gov.uk</u> ↗ 03708 506 506

### **Overview of findings and recommendations**

To save you time when assessing the report, we only provide maps and data tables of features within the search radius that we have identified to be of note. These relate to environmental risks that may have liability implications, affect insurance premiums, property values and/or a lender's willingness to lend.

You can view the fully comprehensive library of information we have searched on page 13 >.



#### **Contaminated Land**

The property has passed Groundsure's Contaminated Land Liability assessment. Historical land uses (detailed in the Contaminated Land section of this report) may necessitate further assessment should the property be developed. The Local Planning Authority may formally request this through planning conditions. Occupation and enjoyment of the property for ongoing, continued use should not be affected.

### Ground stability

The property is indicated to lie within an area that could be affected by infilled land. You should consider the following:

#### Next steps for consideration:

- if a survey has been undertaken at the property that considers ground instability and no issues were found, no further action is required
- however, based on the findings of this report, the purchaser should be encouraged to consider potential instability in any future development or alteration of the ground including planting and removing trees, and regardless of the survey outcome
- if no survey has yet been undertaken, we recommend one is carried out by a suitably qualified and experienced person
- if ground instability issues have been or are subsequently identified in a survey we recommend following any advice given in the survey findings
- you should also check whether the property benefits from a current NHBC guarantee or other environmental warranty that often covers structural issues. Please note the presence of an NHBC guarantee wouldn't change the risk assessment of this report

Back to Summary

Contact us with any questions at: info@groundsure.com ↗ 01273 257 755



# Homescreen

#### Non-coal mining areas

The property is assessed to be in a non-coal mining area.

#### Next steps for consideration:

• A more detailed mining search may further clarify the potential risks presented in this report, and unearth records not available to your surveyor. Groundsure GeoRisk can provide a comprehensive assessment of all mining risks and can be ordered through Groundsure or your preferred search provider

#### **Other considerations**

No additional factors that Groundsure believe require further action have been identified in relation to the property.





# Homescreen

### **Environmental summary**



Environmental searches are designed to ensure that significant hazards and risks associated with this property are identified and considered alongside the investment in or purchase of a property. Please see **page 2** > for further advice.



#### **Contaminated Land**

Our Contaminated Land searches have found some potential contamination risks, although these are not considered to be significant under Contaminated Land legislation. If any part of the site was to be (re)developed it is possible that you might have to investigate the presence of contamination from these land uses further. Please see **page 5** > for details of the identified issues and <u>Click here</u>  $\nearrow$  for our assessment methodology.

Contaminated Land Liability	Passed
Past Land Use	Identified
Waste and Landfill	Passed
Current and Recent Industrial	Passed



### Flooding

No significant concerns have been identified as a result of the flood risk searches. No action required.

<u>Click here</u> *¬* for further explanation of the flood risk assessment.

FloodScore<sup>™</sup> insurance rating

Very Low

<b>River and Coastal Flooding</b>	Very Low
Groundwater Flooding	Low
Surface Water Flooding	Negligible
Past Flooding	Not identified
Flood Storage Areas	Not identified

Compiled by Ambiental, a leading flood risk analysis company. <u>Click here</u> *↗* for details.

### Ground stability

The property is assessed to have potential for natural or<br/>non-natural ground subsidence.Natural Gro<br/>Non-NaturalPlease see page 6 > for details of the identified issues.Non-Natural

Natural Ground StabilityLowNon-Natural Ground StabilityIdentified

Rn

Radon

Local levels of radon are considered normal. However, if an underground room makes up part of the accommodation, the property should be tested regardless of radon Affected Area status. Not in a radon affected area



Contact us with any questions at: <u>info@groundsure.com</u> ↗ 01273 257 755



# Homescreen

### Contaminated land / Past land use



C crown copyright and distabase rights 2025. Ordnance Survey licence 100035207

#### Former industrial land use (1:10,560 and 1:10,000 scale)

These historical land uses have been identified from 1:10,560 and 1:10,000 scale Ordnance Survey maps dated from the mid to late 1800s to recent times. They have the potential to have caused ground contamination. Please see the Environmental Summary to find out how these could impact the site.

Please see **page 2** > for further advice.

Distance	Direction	Use	Date
0	on site	Unspecified Works	1983

This data is sourced from Ordnance Survey/Groundsure.







# Homescreen







#### Non-coal mining areas

The property is located in an area that may be affected by surface or sub-surface mining of materials other than coal. Mining may cause ground stability problems such as subsidence, surface collapses, mass movement and landslides, depending on the style of mining used.

Please see **<u>page 2</u>** > for further advice.

#### **Infilled land**

Maps suggest the property is located near a previous pond, quarry, mine, landfill or other hole in the land. These land cavities are often filled with various materials, and this can cause structural problems. Groundsure's experts recommend that you check whether your structural surveys have taken this into account.

Please see **<u>page 2</u>** > for further advice.

Distance	Direction	Use		Da	ite	
7 m	E	Unspecified Hea	ар	19	52	
Ba	ck to Summ	<u>nary</u>	Contact us with any questions at: info@groundsure.com の1273 257 755		Ref: Sample_HomescreenP Your ref: Sample Grid ref: 123456 123456	6



# Homescreen

Groundsure's experts systematically analyse historical maps, which can highlight areas that, over time, may have been filled with various materials. The materials used are usually safe, although in some cases contaminative materials may also have been used. Past ground workings have been identified at the site. These workings may be associated with railway cuttings or other ground engineering but may also indicate mining activity. Information is taken from features identified on Ordnance Survey historical maps, which do not indicate the distance or direction that mines extend beneath the surface. For example, features such as mine shafts only indicate the entrance to a mine. From this, we may infer the potential for underground features to extend outward from this point. Some features within this database may also relate to nonmining underground activities e.g. air shafts for underground railways.



Contact us with any questions at: info@groundsure.com ∧ 01273 257 755 Ref: Sample\_HomescreenP Your ref: Sample Grid ref: 123456 123456

7



# Homescreen

#### **Energy summary**



The property has been identified to lie within 5km of one or more solar energy features or within 10km of one or more wind energy features.

If required, full details on these energy features including a detailed location plan relative to the property are available when you purchase a Groundsure Energy and Transportation Report via your preferred searches provider.



Oil and gas

No historical, active or planned wells or extraction areas	Oil and gas areas	Not identified
have been identified near the property.	Oil and gas wells	Not identified



#### Wind and Solar

Our search of existing and planned renewable wind and solar infrastructure has identified results.

Planned Multiple Wind Turbines	Identified
Planned Single Wind Turbines	Identified
Existing Wind Turbines	Not identified
Proposed Solar Farms	Identified
Existing Solar Farms	Identified



#### **Energy Infrastructure**

Our search of major energy transmission or generation	Power stations	Not identified
infrastructure and nationally significant infrastructure	Energy Infrastructure	Not identified
projects has not identified results.	Projects	Not identified



Contact us with any questions at: info@groundsure.com ↗ 01273 257 755



# Homescreen

### **Transportation summary**



The property has not been identified to lie within the specified distance of one or more of the transportation features detailed below.

If required, full details on these transportation features including a detailed location plan relative to the property are available when you purchase a Groundsure Energy and Transportation Report via your preferred searches provider.



No results for Phase 1 or Phase 2 of the HS2 project (including the 2016 amendments) have been identified within 5km of the property. However, HS2 routes are still under consultation and exact alignments may change in the future.

Visual assessments are only provided by Groundsure if the property is within 2km of Phase 1 and 2a. Other assessments may be available from HS2.

HS2 Route	Not identified
HS2 Safeguarding	Not identified
HS2 Stations	Not identified
HS2 Depots	Not identified
HS2 Noise	Not assessed
HS2 Visual impact	Not assessed



#### Crossrail

The property is not within 250 metres of the Crossrail 2 project.

Crossrail 2 Route	ľ
Crossrail 2 Stations	ľ
Crossrail 2 Worksites	ſ
Crossrail 2 Safeguarding	ľ
Crossrail 2 Headhouse	ſ

Not identified Not identified Not identified Not identified Not identified

#### **Other Railways**

The property is not within 250 metres of any active or former railways, subway lines, DLR lines, subway stations or railway stations.

Active Railways and Tunnels	Not identified
Historical Railways and	Not identified
Tunnels	
Railway and Tube Stations	Not identified
Underground	Not identified



Contact us with any questions at: info@groundsure.com ∧ 01273 257 755



# Homescreen

### **Planning summary**



### **Planning Applications**

Using Local Authority planning information supplied and processed by Serac Tech dating back 7 years, this information is designed to help you understand possible changes to the area around the property. Please note that even successful applications may not have been constructed and new applications for a site can be made if a previous one has failed. We advise that you use this information in conjunction with a visit to the property and seek further expert advice if you are concerned or considering development yourself.

#### 83 Total applications

This total includes mixed and commercial developments within 750m, large residential within 750m, medium residential within 500m, small residential within 250m and home improvement applications within 250m. If required, full details on these applications including a detailed location plan relative to the property are available when you purchase a Groundsure Planning Report via your preferred searches provider.

### Planning constraints

Protected areas have been identified within 50 metres of the property.

Please see **page 11** > for details of the identified issues.

Environmental Protected Areas Not identified Visual and Cultural Protected Identified Areas




Contact us with any questions at: info@groundsure.com ↗ 01273 257 755





# Homescreen

### **Planning constraints**



#### **Conservation Areas**

Conservation Areas exist to protect special architecture and historic interest in an area. It may mean that the property is located in or close to a beautiful or architecturally interesting place to live. There may be extra planning controls restricting some development. This particularly applies to developing the outside of the building and any trees at the property.

Distance	Direction	Name	District
18 m	S	Framlingham	Suffolk Coastal

This data is sourced from Historic England and Local Authorities. For more information please see historicengland.org.uk/listing/what-is-designation/local/conservation-areas/ 7.







# Homescreen

#### **Scheduled Monuments**

Scheduled Monuments have been officially protected as they are considered of national importance. If you are the owner of a scheduled monument and you wish to carry out works to the monument, you will need to apply for prior written permission from the Secretary of State for Culture, Media and Sport. This applies to works above or below ground level.

Scheduled monuments are not always ancient, or visible above ground. There are over 200 'classes' of monuments, ranging from prehistoric standing stones, through to many types of medieval site - castles, monasteries, abandoned farmsteads - to the more recent results of human activity, such as collieries.

Scheduling is reserved for carefully selected sites, which create a representative sample of sites from different epochs. Please see Historic England's website for further information.

Distance	Direction	Ancient Monument Name	Listed Entry
39 m	NW	Framlingham Castle and its associated landscape including the mere, town ditch and Anglo-Saxon cemetery	1002965



Contact us with any questions at: info@groundsure.com ↗ 01273 257 755





### Homescreen

#### **Datasets searched**

This is a full list of the data searched in this report. If we have found results of note we will state "Identified". If no results of note are found, we will state "Not identified". Our intelligent filtering will hide "Not identified" sections to speed up your workflow.

#### **Contaminated Land** Former industrial land use (1:10,560 and Identified 1:10,000 scale) Former tanks Not identified Former energy features Not identified Not identified Former petrol stations Not identified Former garages Former military land Not identified Former landfill (from Local Authority and Not identified historical mapping records) Waste site no longer in use Not identified Active or recent landfill Not identified Former landfill (from Environment Agency Not identified Records) Active or recent licensed waste sites Not identified Recent industrial land uses Not identified Current or recent petrol stations Not identified Hazardous substance storage/usage Not identified Sites designated as Contaminated Land Not identified Historical licensed industrial activities Not identified Current or recent licensed industrial Not identified activities Local Authority licensed pollutant release Not identified Pollutant release to surface waters Not identified Pollutant release to public sewer Not identified Dangerous industrial substances (D.S.I. Not identified List 1)

Contaminated Land				
Dangerous industrial substances (D.S.I. List 2)	Not identified			
Pollution incidents	Not identified			
Flooding				
Risk of flooding from rivers and the sea	Not identified			
Flood storage areas: part of floodplain	Not identified			
Historical flood areas	Not identified			
Reduction in Risk of Flooding from Rivers and Sea due to Defences	Not identified			
Flood defences	Not identified			
Proposed flood defences	Not identified			
Surface water flood risk	Not identified			
Groundwater flooding	Not identified			
Natural ground subsidence				
Natural ground subsidence	Not identified			
Natural geological cavities	Not identified			
Non-natural ground subsidence				
Coal mining	Not identified			
Non-coal mining areas	Identified			
Non-coal mining	Not identified			
Mining cavities	Not identified			
Infilled land	Identified			



Contact us with any questions at: info@groundsure.com ↗ 01273 257 755



# Homescreen

Radon				
Radon	Not identified			
Energy				
Electricity transmission lines and pylons	Not identified			
Planning constraints				
Sites of Special Scientific Interest	Not identified			
Internationally important wetland sites (Ramsar Sites)	Not identified			
Special Areas of Conservation	Not identified			
Special Protection Areas (for birds)	Not identified			
National Nature Reserves	Not identified			
Local Nature Reserves	Not identified			
Designated Ancient Woodland	Not identified			
Green Belt	Not identified			
World Heritage Sites	Not identified			
Areas of Outstanding Natural Beauty	Not identified			
National Parks	Not identified			
Conservation Areas	Identified			
Listed Buildings	Not identified			
Certificates of Immunity from Listing	Not identified			
Scheduled Monuments	Identified			
Registered Parks and Gardens	Not identified			

Back to Summary

Contact us with any questions at: info@groundsure.com ↗ 01273 257 755





# Homescreen

### **Methodologies and limitations**

Groundsure's methodologies and limitations are available here: <u>knowledge.groundsure.com/methodologies-and-limitations</u> **7**.

### **Data providers**

Groundsure works with respected data providers to bring you the most relevant and accurate information in your Homescreen report. To find out who they are and their areas of expertise see <u>www.groundsure.com/sources-reference</u>  $\nearrow$ .

### **Conveyancing Information Executive and our terms & conditions**

#### IMPORTANT CONSUMER PROTECTION INFORMATION

This search has been produced by Groundsure Ltd. Groundsure adheres to the Conveyancing Information Executive Standards.

In addition to The Property Ombudsman (TPO) redress scheme covering consumers, TPO will also provide redress to small businesses (including Charities and Trusts) and where the customer meets the following criteria:

- a small business (or group of companies) with an annual turnover of less than £3 million;
- a charity with an annual income of less than £3 million;
- a Trust with a net asset value of less than £3 million.

#### **Complaints Advice**

If you have a query or complaint about your search, you should raise it directly with the search firm, and if appropriate ask for any complaint to be considered under their formal internal complaints procedure.

If you remain dissatisfied with the firm's final response, after your complaint has been formally considered, or if the firm has exceeded the response timescales, you may refer your complaint for consideration under The Property Ombudsman scheme (TPOs). The Ombudsman can award up to £5,000 to you if the Ombudsman finds that you have suffered actual financial loss and/or aggravation, distress or inconvenience as a result of your search provider failing to keep to the Standards.

Please note that all queries or complaints regarding your search should be directed to your search provider in the first instance, not to TPOs.

#### COMPLAINTS PROCEDURE: If you want to make a complaint, we will:

- acknowledge it within 5 working days of receipt
- normally deal with it fully and provide a final response, in writing, within 20 working days of receipt
- liaise, at your request, with anyone acting formally on your behalf

#### Complaints should be sent to:

Operations Director, Groundsure Ltd, Nile House, Nile Street, Brighton, BN1 1HW. Tel: 01273 257 755. Email: <u>info@groundsure.com</u> If you are not satisfied with our final response, or if we exceed the response timescales, you may refer the complaint to The Property Ombudsman scheme (TPOs): Tel: 01722 333306, E-mail: <u>admin@tpos.co.uk</u> I We will co-operate fully with the Ombudsman during an investigation and comply with their final decision.

Groundsure's Terms and Conditions can be viewed here: www.groundsure.com/terms-and-conditions-april-2023/ 7

All of the advice and reports that Groundsure produces are covered by a comprehensive Remediation Contribution policy to ensure customers are protected, see <u>www.groundsure.com/remediation</u> 7 for full details.



Contact us with any questions at: info@groundsure.com ↗ 01273 257 755

